



Catálogo Medalhas Metálicas

960371501

mail@ carimbos.net

www.carimbos.net



ART
D4A.01
D4A.02
D4A.27

Ø	T
50	2
50	2
50	2



ART
D28A.01
D28A.02
D28A.27

Ø	T
50	2
50	2
50	2



ART
D28B.01
D28B.02
D28B.27

Ø	T
50	2
50	2
50	2



ART
D28C.01
D28C.02
D28C.27

Ø	T
50	2
50	2
50	2



ART
D28F.01
D28F.02
D28F.27

Ø	T
50	2
50	2
50	2




ART
D112D.01
D112D.02
D112D.26

Ø	T
50	2
50	2
50	2




ART
D112E.01
D112F.02
D112G.26

Ø	T
50	2
50	2
50	2



ART
D112H.01
D112H.02
D112H.26

Ø	T
50	2
50	2
50	2



ART
D15001.01
D15001.02
D15001.26

Ø	T
50	2
50	2
50	2



ART
D15002.01
D15002.02
D15002.26

Ø	T
50	2
50	2
50	2





ART
D12A.01
D12A.02
D12A.27

Ø	T
40	3
40	3
40	3



ART
D12B.01
D12B.02
D12B.27

Ø	T
40	3
40	3
40	3



ART
D12C.01
D12C.02
D12C.27

Ø	T
40	3
40	3
40	3



ART
DZ4001.01
DZ4001.02
DZ4001.27

Ø	T
40	2
40	2
40	2



ART
DZ4002.01
DZ4002.02
DZ4002.27

Ø	T
40	2
40	2
40	2





ART
D10.01
D10.02
D10.26

Ø	T
45	1.5
45	1.5
45	1.5



ART
D17A.01
D17A.02
D17A.27

Ø	T
45	2
45	2
45	2



ART
D70.01
D70.02
D70.27

Ø	T
45	2
45	2
45	2



ART
D110.01
D110.02
D110.26

Ø	T
45	2
45	2
45	2





ART
D14501.01
D14501.02
D14501.26

Ø	T
45	2
45	2
45	2



ART
D11D.01
D11D.02
D11D.12

Ø	T
45	2
45	2
45	2



ART
D11T.01
D11T.02
D11T.12

Ø	T
45	2
45	2
45	2




ART
D6A.01
D6A.02
D6A.27

Ø	T
45	3
45	3
45	3



ART
D30.01
D30.02
D30.27

Ø	T
50	2
50	2
50	2



ART
D111.01
D111.02
D111.26

Ø	T
50	2
50	2
50	2



ART
D112A.01
D112A.02
D112A.26

Ø	T
50	2
50	2
50	2



ART
D112B.01
D112B.02
D112B.26

Ø	T
50	2
50	2
50	2



ART
D112C.01
D112C.02
D112C.26

Ø	T
50	2
50	2
50	2



ART
D28G.01
D28G.02
D28G.27


Ø	T
50	2
50	2
50	2



Z

ART
D28J.01
D28J.02
D28J.27

Ø	T
50	2
50	2
50	2



Z

ART
D39.01
D39.02
D39.27

Ø	T
50	3
50	3
50	3



Z

ART
D45.01
D45.02
D45.27

Ø	T
50	2
50	2
50	2



Z

ART
D50B.12
D50B.67
D50B.27

Ø	T
50	2
50	2
50	2




Z



ART
D61.01
D61.02
D61.27

Ø T
50 2
50 2
50 2

HP



ART
D71.01
D71.02
D71.27

Ø T
50 2
50 2
50 2

Z



ART
D77A.01
D77A.02
D77A.27

Ø T
50 3
50 3
50 3

Z



ART
D77B.01
D77B.02
D77B.27

Ø T
50 3
50 3
50 3

Z



ART
D77C.01
D77C.02
D77C.27

Ø T
50 3
50 3
50 3

Z





ART
D79A.01
D79A.02
D79A.27

Ø	T
50	2
50	2
50	2

Z



ART
D81.01
D81.02
D81.27

Ø	T
50	2
50	2
50	2

HP



ART
D82.01
D82.02
D82.27

Ø	T
50	2
50	2
50	2

HP



ART
D84.01
D84.02
D84.27

Ø	T
50	2
50	2
50	2


HP



ART
D87.01
D87.02
D87.27


Ø	T
50	2
50	2
50	2

Z




ART
D7J.12
D7J.67
D7J.27

Ø	T
50	2
50	2
50	2



ART
D44.01
D44.02
D44.27

Ø	T
50	2
50	2
50	2




ART
D48.01
D48.02
D48.27

Ø	T
50	3
50	3
50	3



ART
D49.01
D49.02
D49.27

Ø	T
50	3
50	3
50	3



ART
DZ5002.01
DZ5002.02
DZ5002.27

Ø	T
50	2
50	2
50	2

